



Final compliance report

FINAL COMPLIANCE EVALUATION REPORT

COATING : Asset

Client: FIELD EAGLE

Location: STEVE MELO FIELD EAGLE DEMO (REVISED)

Vehicle Type: 2018 Ford Edge

Report No.: STEVE MELO FIELD EAGLE DEMO (REVISED)-1

Date: 15 Nov 2024 16:16:48

Issued by: Steve Melo

Inspector: Steve Melo

Contact

Contact Person:	Contact Email:
-----------------	----------------

Contact #: STEVE MELO FIELD EAGLE DEMO (R	Purchase Order/Reference #: 1
---	-------------------------------

Disclaimer

This report and the recommendations contained within are based upon the reviewed condition and observations noted by the attending surveyors at the time of inspection, and information made available to personnel.




Final compliance report

Report Chart

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

■ Compliant
 ■ Non-Compliant



Category	Compliant	Non-compliant
No category	57%	43%

INS/Auditor Signature:	
Print name:	Steve Melo
Date:	15 Nov 2024 16:16:48



Final compliance report

Punch List Details

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Non-Compliant Question

Radio Operational

Recommandation / Note

All stations have static

Photo



Final compliance report

Punch List Details

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Non-Compliant Question

Windshield Free of Cracks and Chips

Recommandation / Note

Crack in whindshield

Photo





Final compliance report

Punch List Details

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Non-Compliant Question

Rear Driver Tire Pressure (PSI)

Recommandation / Note

leak in tire

Photo





Final compliance report

Expanded Punch List Details

Compliant - Nor-Lag workers can proceed with the completion of the next phase of work.

Non-Compliant - Nor-Lag workers must refrain from completing the next phase of work until the non-compliant element is corrected and re-inspected by a Nor-Lag authorized inspectors.

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Inspected Component	Current Condition	Recommendations/Notes	Photos	
Vehicle Type	2018 Ford Edge			
Vehicle Colour	Blue			
Have Instructions been reviewed?	Yes			
Photograph of the Vehicle Being Inspected:	Photo Taken			
Prepared by:	Steve Melo			
Date of Inspection:	Nov 15th, 2024			
Company	Field Eagle			
Plate Number	1234 567			



Final compliance report

Expanded Punch List Details

Compliant - Nor-Lag workers can proceed with the completion of the next phase of work.

Non-Compliant - Nor-Lag workers must refrain from completing the next phase of work until the non-compliant element is corrected and re-inspected by a Nor-Lag authorized inspectors.

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Inspected Component	Current Condition	Recommendations/Notes	Photos	
Current Mileage (KM):	1200			
Fuel Level:	Full			
Windscreen Wipers Functioning Appropriately	Yes			
Horn Functioning Appropriately	Yes			
Heat and Defroster Operational	Yes			
Air Conditioning Operational	Yes			
Dashboard Lights Operational	Yes			
Radio Operational	No	All stations have static		




Final compliance report

Expanded Punch List Details

Compliant - Nor-Lag workers can proceed with the completion of the next phase of work.

Non-Compliant - Nor-Lag workers must refrain from completing the next phase of work until the non-compliant element is corrected and re-inspected by a Nor-Lag authorized inspectors.

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Inspected Component	Current Condition	Recommendations/Notes	Photos	
Driver Seat in Good Repair	Yes			
Passenger Seats in Good Repair	Yes			
Driver Seat Belt Operational	Yes			
Passenger Seat Belts Operational	Yes			
Windshield Free of Cracks and Chips	No	Crack in whindshield		
Front Hood, Grill and Bumper Free of Damage	Yes			
Mirrors Adjustable and Free of Damage	Yes			
Tires in Good Repair with No Visible Signs of Wear or Cracking in Sidewall	Yes			



Final compliance report

Expanded Punch List Details

Compliant - Nor-Lag workers can proceed with the completion of the next phase of work.

Non-Compliant - Nor-Lag workers must refrain from completing the next phase of work until the non-compliant element is corrected and re-inspected by a Nor-Lag authorized inspectors.

Location	Inspection Date	Inspector	Inspection Type	Vehicle Type
STEVE MELO FIELD EAGLE DEMO (REVISED)	15 Nov 2024 16:16:48	Steve Melo	STEVE MELO FIELD EAGLE DEMO (REVISED)	2018 Ford Edge

Inspected Component	Current Condition	Recommendations/Notes	Photos	
Vehicle Type	Sedan; SUV; Van - Between 35 to 40 PS			
Front Driver Tire Pressure (PSI)	36			
Front Passenger Tire Pressure (PSI)	38			
Rear Passenger Tire Pressure (PSI)	37			
Rear Driver Tire Pressure (PSI)	32	leak in tire	